

Mine Name: Solar Wind

Operator Name: Utah Minerals and Fossil Inc.

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program

May 18, 2009

Reviewed	AUNT

Permit Number: S/023/0061

Inspection Date: 05/14/2009

1 M

operator traine. Otali Willerais and 1 05511 file.	Inspection Date. 03/14/2009			
Inspector(s): Wayne Western & Brett Gregory	Time: 4:00 – 4:40 pm Mine Status: Suspended			
Other Participants: None				
Elements of Inspection	Evaluated	Comment	Enforcement	
 Permits, Revisions, Transfer, Bonds Public Safety (shafts, adits, trash, signs, highwalls) Protection of Drainages / Erosion Control Deleterious Material Roads (maintenance, surfacing, dust control, safety) Reclamation Backfilling/Grading (trenches, pits, roads, highwalls, Soils Revegetation 				

Bond Renewal Date: None listed **Bond Amount:** \$ 5,365. No permit fee has been received

Purpose of Inspection: Routine annual Inspection.

<u>Inspection Summary</u>: This site consists of a small disturbance, probably less than a couple of acres in size, including the road. No new improvement to the access road. Mine site with dump was 0.4 acres of disturbance.

Photos were taken to document site conditions.

The records indicate that the fees have not been paid since 2006.

On May 18, 2009, Wayne Western contacted the Permittee, who stated that fees would be paid by June 30, 2009.

<u>Conclusions and Recommendations</u>: DOGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature

WHW:BG::pb

cc: John Holfert, Operator


Sheri Wysong, BLM, Fillmore FO

Attach - GIS

 $O: \label{lem:constraint} O: \label{lem:co$



Inspection Date: May 14, 2009 Page 2 of 2 S/023/0061



Ground disturbance.



Overburden dumps.

